



Product End-of-Life Disassembly Instructions

Product Category: Inkjet Printers

Marketing Name / Model

[List multiple models if applicable.]

DJ500 / C7769B-C7770B

DJ500ps / C7769C-C7770C

DJ500 mono / C7769E-C7770E

DJ500 Plus / C7769F-C7770F

DJ500ps Plus / C7769G-C7770G

DJ800 / C7779B-C7780B

DJ800ps / C7779C-C7780C

Purpose: The document is intended for use by end-of-life recyclers or treatment facilities. It provides the basic instructions for the disassembly of HP products to remove components and materials requiring selective treatment, as defined by EU directive 2002/96/EC, Waste Electrical and Electronic Equipment (WEEE).

1.0 Items Requiring Selective Treatment

1.1 Items listed below are classified as requiring selective treatment.

Item Description	Notes	Quantity of items included in product
Printed Circuit Boards (PCB) or Printed Circuit Assemblies (PCA)	With a surface greater than 10 sq cm	7 (DJ500, DJ500ps, DJ500 mono) 8 (DJ500 Plus, DJ500ps Plus) 9 (DJ800ps) 10 (DJ800)
Batteries	All types including standard alkaline and lithium coin or button style batteries:	0
Mercury-containing components	For example, mercury in lamps, display backlights, scanner lamps, switches, batteries	0
Liquid Crystal Displays (LCD) with a surface greater than 100 sq cm	Includes background illuminated displays with gas discharge lamps	0
Cathode Ray Tubes (CRT)		0
Capacitors / condensers (Containing PCB/PCT)		0
Electrolytic Capacitors / Condensers measuring greater than 2.5 cm in diameter or height	Located in Main PCA and Power Supply assy PCA	10
External electrical cables and cords	Power cable for all models + USB comm. cable in 2 models	2 (DJ500ps) 1 (The rest of models)
Gas Discharge Lamps		0
Plastics containing Brominated Flame Retardants		0

Components and parts containing toner and ink, including liquids, semi-liquids (gel/paste) and toner	4 printheads, 4 ink supplies, Spittoon assembly, Service Station Assembly, Tubes assembly	11
Components and waste containing asbestos		0
Components, parts and materials containing refractory ceramic fibers		0
Components, parts and materials containing radioactive substances		0

2.0 Tools Required

Tool Description	Tool Size (if applicable)
Small flat- blade screwdriver	
Nut Driver with attachments	5.5 mm & 3/16 inch
Long Torx Screwdriver with attachments	8-9-10-15-20-15L

3.0 Product Disassembly Process

3.1 List of the basic steps:


1. Follow the Graphic instruction 1 to segregate components containing ink.
2. Follow the Graphic instruction 2, 3, 4 & 5 to disassembly external covers.
3. Follow the Graphic instructions 6, 7, 8, 9 & 10 to segregate PCA, PCB and condensers.
4. Follow the Graphic instructions 11 (#1) & 12 (#1 & #3) to segregate parts of the showed assemblies containing ink.

3.2 Graphics.


Graphic 1:




Graphic 2:




Graphic 3:




Graphic 4:




Graphic 5:




Graphic 6:




Graphic 7:




Graphic 8:




Graphic 9:



Graphic 10:



Graphic 11:



Graphic 12:

